

Carrier Screen, Focused Panel, Varies

Test ID: CSFP

Explanation:

Effective immediately, CSFP will be delayed for up to two weeks due to instrumentation issues. There is no testing alternative available. Samples will be extracted, stabilized, and held to be run once the equipment is fixed. Updates will be provided as they occur.

Questions

Contact Michelle Rath, Laboratory Technologist Resource Coordinator at 800-533-1710.